

Prep Computer and Mask

On Computer Confirm Water, Tank Size and O2%

On Computer Confirm Date/Time/Zone

Put Anti-Fog in Primary Mask and Set Aside

Prep BCD

Confirm Spare Bolt Snap Attached Left Shoulder DRing

Confirm Dive Light Attached Right Shoulder DRing

Confirm Dive Light Attached Left Shoulder DRing

Attach BCD to Tank

Attach Tank

Attach 1st Stage to Tank

Clip Primary 2nd Stage to Right Shoulder DRing

Clip Necklace 2nd Stage to Right Shoulder DRing

Attach Power Inflator and Route Properly

Route and Clip SPG to Left Hip DRing

Check Air Pressure

Turn Air Fully On

Check Computer has >2500 psi

Check SPG has >2500 psi

As of Aug 15, 2024

Check Air Delivery
Inflate & Deflate BCD
Breath off Primary 2nd Stage and Stow
Breath off Backup 2nd Stage and Stow
Weights
Place Weight in Tank Trim Pockets
Place Weight in Drop Pockets and Set Aside
Exposure Suit (Dry)
Check Neck and Wrist Seals
Silicon Spray Dry Suit Glove Ring
Exposure Suit Partially On
Computer on Right Wrist
Compass on Left Wrist
Confirm dSMB + Spool in Left Thigh Pocket
Confirm Dive Slate / Wet Notes in Right Thigh Pocket
Confirm Spare Mask in Right Thigh Pocket
Optional Items
Confirm Flasher Attached Left Shoulder DRing
Confirm Dive Reel attached Butt DRing
Confirm Mirror & Whistle in Right Thigh Pocket Flap
Confirm Spare Spool in Right Thigh Pocket

As of Aug 15, 2024

Final Checklist

Finish Suit Up
Dry Suit Fully On
Burp Dry Suit or Cool Down Burp in Water
Dry Suit Gloves On
Dry Suit Inflator Attached
BCD On and Buckled
One tap of Dry Suit Inflator
Pre Jump / Pre Walk
Confirm Backup 2nd Stage Venturi Is Off
Breath off Backup 2nd Stage and Stow
Confirm Primary 2nd Stage Venturi is On
Breath off Primary 2nd Stage and Stow
Partially Inflate BCD
Check Air Pressure is >2500 psi
Good To Go
Load Dump Weight Pockets (<i>In Hand if Walking</i>)
Mask On (<i>On Head if Walking</i>)
Fins On (<i>Clipped Off if Walking</i>)

As of Aug 15, 2024